



SOLAR BAT® SUNGLASSES

Thank you for purchasing Solar Bat® Leverage Performance Glasses. Leverage Glasses meet or exceed all U.S. Government standards for impact resistance but may not be worn as safety glasses.

WHEN REMOVING GLASSES USE BOTH HANDS, AS THIS WILL KEEP YOUR GLASSES FITTING SNUGLY ON YOUR HEAD.

CLEANING AND CARE OF LEVERAGE PNVXD LENSES:

1. Clean lenses first by rinsing with water and then use a soft dry cloth or the microfiber pouch included with your sunglasses to wipe the lenses dry.
2. Heavily soiled lenses should first be washed with warm soapy water (use a mild soap like dish washing detergent) then dried with a clean soft cloth.
3. If exposed to salt water spray rinse lenses and frames thoroughly under running water to avoid corrosion.
4. Always store your glasses in their protective case.
5. Never expose your sunglasses to extreme temperatures such as storing in your automobile on very hot or cold days.
6. After use wipe all sunscreen from the temples and bridge of your frames to avoid frame damage from the chemicals present in these lotions.
7. Clean mirrored lenses with water or warm soapy water only as the chemicals in many lens cleaning preparations can damage the mirror coating on the lenses.

Lenses have a double thickness scratch resistant coating but are NOT scratch proof. Following the above instructions will ensure many years of enjoyable wear.

SOLAR BAT® ACCESSORIES

Hats, T-shirts, denim shirts, sweatshirts, lanyards, decals, and patches are available by calling Solar Bat® at 1-800-761-8228. You can view accessories and the full line of Solar Bat® sunglasses at www.solarbat.com.

WARRANTY

Your glasses have a 90-day warranty on Manufacturer's defects. Simply return the glasses to Solar Bat® for replacement or repair. After 90 days, any broken frame part will be replaced for shipping and handling and lenses will be replaced for \$15.00 per lens for as long as you own the glasses. Solar Bat® reserves the right to substitute frame styles if frame style has been discontinued.

RETURN WARRANTY REPAIRS TO: Solar Bat® Enterprises, Inc., 3628 East County Road 600 N., Brazil, IN 47834. You must include your name, address, phone number and charge card information inside the box with all glasses returned for warranty repair.

DATE OF PURCHASE FOR YOUR RECORDS _____

Cut and mail bottom portion.

SOLAR BAT® LEVERAGE WARRANTY REGISTRATION

Name _____ Phone _____

Address _____ City _____

State _____ Zip Code _____ Frame style _____

Lens tint _____ Date of Purchase _____ Price _____

Dealer _____ Comments _____

Email Address to receive press releases _____

RETURN WITHIN 14 DAYS OF DATE OF PURCHASE WITH PROOF OF PURCHASE TO:

Solar Bat® South, 6116 Highway 515, Suite H, Ellijay, GA 30536 ATTN: Warranty Registration